Tom E. Tynan Vice President Vogtle -Units 1 & 2 Southern Nuclear Operating Company, Inc. 7821 River Road Waynesboro, GA 30830

Tel 706.826.3151 Fax 205.980.3321



December 13, 2013

Docket Nos.: 50-425

NL-13-2489

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

Vogtle Electric Generating Plant
Licensee Event Report 2-2013-002-00
Automatic Unit 2 Reactor Trip Due To Loss Of Generator Excitation

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company (SNC) is submitting the enclosed Licensee Event Report, 2-2013-002.

This letter contains no NRC commitments. If you have any questions, please contact Ken McElroy at (205) 992-7369.

Respectfully submitted,

9. L. Tyran

T. E. Tynan

Vice President - Vogtle

TET/KCW

Enclosure: Unit 2 Licensee Event Report 2-2013-002-00

cc: Southern Nuclear Operating Company

Mr. S. E. Kuczynski, Chairman, President & CEO

Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer

Mr. T. E. Tynan, Vice President - Vogtle

Mr. B. L. Ivey, Vice President - Regulatory Affairs

Mr. B. J. Adams, Vice President - Fleet Operations

Mr. D. L. Manigo, OE Coordinator - Vogtle

RType: CVC7000

U. S. Nuclear Regulatory Commission

Mr. V. M. McCree, Regional Administrator

Mr. R. E. Martin, NRR Senior Project Manager - Vogtle

Mr. L. M. Cain, Senior Resident Inspector - Vogtle

Vogtle Electric Generating Plant – Unit 2 Licensee Event Report 2-2013-002-00 Automatic Unit 2 Reactor Trip Due To Loss Of Generator Excitation

Enclosure

Unit 2 Licensee Event Report 2-2013-002-00

		U.S. NUCLI	EAR RI	GULATOR	RY COMMI	ISSION /	PPROVE	D BY OMB	: NO. 3150-010	4	EXPIRES:	10/31/2013	
Estimated burden per response to comply with this mandatory colle request: 80 hours. Reported lessons learned are incorporated into licensing process and fed back to industry. Send comments regarding by estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regul Commission, Washington, DC 20555-0001, or by internet e-mainfocollects.resource@nrc.gov, and to the Desk Officer, Office of Inform and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Managemen Budget, Washington, DC 20503. If a means used to impose an inform collection does not display a currently valid OMB control number, the NRC not conduct or sponsor, and a person is not required to respond to									tred into the arding burden in Regulatory et e-mail to off Information agement and in information the NRC may				
1. FACILITY NAME Vogtle Electric Generating Plant						2		DOCKET NUMBER 3. PAGE					
4. TITLE													
							T	8.	OTHER FAC	ILITIES INVO) VED		
YEAR	YEAR		1	MONTH	DAY	YEAR	FACILITY N/A		OTTLITTAG	in the state of th	DOCKET	NUMBER V/A	
2013	2013	- 02 -	00	12	13	13	FACILITY N/A	NAME			DOCKET	NUMBER V/A	
MODE	11.	THIS REPO	RT IS	SUBMITTI	ED PURS	UANT TO	THE RE	QUIREM	ENTS OF 10	CFR§: (Chec	ck all that	apply)	
1			☐ 20.2203(a)(3)(i) ☐ 20.2203(a)(3)(ii) ☐ 20.2203(a)(4) ☐ 50.36(c)(1)(i)(A) ☐ 50.36(c)(1)(ii)(A) ☐ 50.36(c)(2) ☐ 50.46(a)(3)(ii) ☐ 50.73(a)(2)(i)(A) ☐ 50.73(a)(2)(i)(B)			☐ 50.73(a)(2)(i)(C) ☐ 50.73(a)(2)(ii)(A) ☐ 50.73(a)(2)(ii)(B) ☐ 50.73(a)(2)(iii) ☐ 50.73(a)(2)(iv)(A) ☐ 50.73(a)(2)(v)(A) ☐ 50.73(a)(2)(v)(B) ☐ 50.73(a)(2)(v)(C) ☐ 50.73(a)(2)(v)(D)			☐ 50.73(a)(2)(vii) ☐ 50.73(a)(2)(viii)(A) ☐ 50.73(a)(2)(viii)(B) ☐ 50.73(a)(2)(ix)(A) ☐ 50.73(a)(2)(ix)(A) ☐ 73.71(a)(4) ☐ 73.71(a)(5) ☐ OTHER Specify in Abstract below or in NRC Form 366A				
			1	2. LICENS	SEE CONT	TACT FO	R THIS L	.ER					
FACILITY NAME Vogtle Electric Generating Plant / Kevin Walden TELEPHONE NUMBER (Include Area Code) (706) 826-4290													
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT													
SYSTEM	COMPO					CAI	JSE	SYSTEM	COMPONENT	MANU- FACTURER			
1328	P5C	02 G	Е	N	О	N	N/A N/A N/A		N/A	N/A	1	V/A	
14	. SUPPLI	EMENTAL RI	EPOR	T EXPECT	ED	···				монтн	DAY	YEAR	
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)						⊠ I	10		N/A	N/A	N/A		
On October 19, 2013 at approximately 0645 Eastern Daylight Time (EDT), Vogtle Unit 2 was operating in Mode 1 at 100% power. The main generator excitation system experienced a failure which tripped the Main Generator which subsequently tripped the Turbine and Reactor. The Reactor Trip System, the Engineered Safety Feature Actuation System, and other responding equipment performed as expected. The plant was stabilized in Mode 3. The cause of the event was a failure of the Main Generator excitation system. The safety significance of this event is very low. Unit 1 was not affected and there were no adverse effects of the health and safety of the public.													
	AME lectric G lic Unit 2 DATE YEAR 2013 A MODE SYSTEM 1328 14 es, complete mit to 1400 ber 19, ng in Moripped the Trip Syent performit perfor	AME lectric Genera ic Unit 2 Reacto DATE 6. L YEAR YEAR 2013 2013 A MODE 11. 20.22 2	AME lectric Generating Plan	AME Icetric Generating Plant	AME Iceric Generating Plant Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor Trip due loss of Geres Ice Unit 2 Reactor No. Ice Unit 3 Reactor No. Ice Unit 4 Ice Un	AME Rectric Generating Plant C Unit 2 Reactor Trip due loss of Generator DATE SEQUENTIAL REV MONTH DAY YEAR YEAR SEQUENTIAL REV MONTH DAY 2013 2013 - 02 - 00 12 13 AMODE 11. THIS REPORT IS SUBMITTED PURSI 20.2201(b)	AME lectric Generating Plant ic Unit 2 Reactor Trip due loss of Generator Excitation DATE YEAR YEAR SEQUENTIAL REV MONTH DAY YEAR 2013 2013 - 02 - 00 12 13 13 3 MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO 20.2201(b) 20.2203(a)(3)(i) 20.2203(a)(3)(i) 20.2203(a)(2)(i) 20.2203(a)(3)(i) 20.2203(a)(2)(i) 50.36(c)(1)(i)(A) 20.2203(a)(2)(ii) 50.36(c)(1)(ii)(A) 50.2203(a)(2)(ii) 50.36(c)(1)(ii)(A) 20.2203(a)(2)(iv) 50.73(a)(2)(i)(B) 20.2203(a)(2)(v) 50.73(a)(2)(i)(B) 20.2203(a)(2)(ii) 50.73(a)(2)(ii)(B) 20.2203(a)(2)(ii) 50.73(a)(2)(ii) 20.2203(a)(2)(ii) 50.73(a)(2)(ii) 20.2203(a)(LICENSEE EVENT REPORT (LER) Estimated request: 8 licensing positimate its commission of collection of not conducting programment of the conducting programment progra	LICENSEE EVENT REPORT (LER) Stimated burden perquest: 80 hours. Figures: 81 hours. Figures: 82 hours. Figures: 82 hours. Figures: 84 hours. Figures: 84 hours. Figures: 84 hours. Figures: 84 hours. Figures: 85 hours. Figures: 85 hours. Figures: 85 hours. Figures: 86 hours. Figures: 86 hours. Figures: 86 hours. Figures: 86 hours. Figures: 87 hours. Figures: 87 hours. Figures: 88 hours. Fig	Estimated burden per response to request. 80 hours. Reported lessor estimated burden per response to request. 80 hours. Reported lessor estimate to the Fold/Privacy Section Commission, Washington, Dc. 20th indicates the source of micropy, and to and Regulatory Allairs, NEOS-10202. Indicates the source of micropy and to and Regulatory Allairs, NEOS-10202. Indicates the source of micropy and to and Regulatory Allairs, NEOS-10202. Indicates the source of micropy and the source of micropy and and Regulatory Allairs, NEOS-10202. Indicates the source of micropy and and Regulatory Allairs, NEOS-10202. Indicates the source of micropy and and Regulatory Allairs, NEOS-10202. Indicates the source of the	LICENSEE EVENT REPORT (LER) Commission Part Report Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part Part	LICENSEE EVENT REPORT (LER) Compose Compo	

LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET										
1. FACILITY I	NAME	2. DOCKET	6. LER NUMBER				3. PAGE			
Vogtle Electric Generating I	Plant	05000-425	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	a		
Vogao Zicotho donorating i		00000 120	2013	- 02 -	00	_	01	U		

NARRATIVE

A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73(a)(2)(iv)(A) as there was an unplanned automatic actuation of the Reactor Protection System (RPS) and an automatic actuation of the Auxiliary Feedwater System (AFW).

B. UNIT STATUS AT TIME OF EVENT

Mode 1, 100% power

C. DESCRIPTION OF EVENT

While operating at 100% power with no abnormal indications, Unit 2 experienced a loss of generator excitation which tripped the Main Generator. This resulted in a Reactor Protection System (RPS) actuation due to a Turbine Trip above the P9 setpoint of 40% which shut down the reactor. The Auxiliary Feedwater System (AFW) actuated as Main Feedwater isolated when the RPS actuated. All rods inserted and the plant was stabilized in Mode 3 and no complications were experienced during the trip as all systems responded as designed.

D. CAUSE OF EVENT

The probable cause of the event was an intermittent fault in the Main Generator de-excitation control circuitry.

E. SAFETY ASSESSMENT

When the reactor tripped, all rods fully inserted. As a result of the reactor trip, the Feedwater System isolated and the Auxiliary Feedwater System actuated as designed. The unit was stabilized in Mode 3 at the applicable temperature and pressure. Because the plant responded as designed and there were no complications with the plant shutdown, there was no adverse effect on plant safety or the safety and health of the public.

F. CORRECTIVE ACTION

Following the failure of the de-excitation control circuitry of the EX2100 generator excitation system, three controller cards and a breaker were replaced within the de-excitation system at the recommendation General Electric.

NRC FORM 366A LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET										
1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE						
Vogtle Electric Generating Plant	05000-425	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	3			
Vogao Elocato denerating Flant	00000 420	2013	- 02 -	00		O1	Ü			

NARRATIVE

G. ADDITIONAL INFORMATION

- 1) Failed Components: General Electric EX-2100 generator de-excitation control circuitry.
- 2) Previous Similar Events: ICES 235585 Bruce 6 Turbine Trips Due to Loss of Excitation
- 3) Energy Industry Identification System Code:

[TL] - Main Generator Excitation System

[JC] - Reactor Protection System

[BA] - Auxiliary Feedwater System

4) Other Systems Affected:

None

5) Commitment Information:

This report does not create any commitments.